





Figure 2. Side view of fiber stress testing apparatus. A simple lever can be constructed using a metal hinge and standard 2" X 4" pine boards.